

Manor Vale Wood, Kirkbymoorside

| Ref No: | Species | Comments | Preliminary Management Recommendations |
|---------|---|---|--|
| 0136 | Ash Eastern side of top track | Large dead branch extending over track | Pollard below crown emergence |
| 0138 | Ash (Young) On roadside leading to golf course | Dead, hanging over footpath | Fell |
| 0139 | Ash (semi-mature) On roadside leading to golf course | Extensive die-back | Pollard to a practical level |
| 0140 | Ash (semi-mature) On roadside leading to golf course | Extensive die-back | Pollard to a practical level |
| 0141 | Elm(semi-mature) On roadside leading to golf course | Extensive die-back | Pollard to a practical level |
| 0142 | Ash(Mature) On roadside leading to golf course | Extensive die-back over road) | Pollard to a practical level |
| 0142 | Ash(Mature) On roadside leading to golf course | Extensive die-back over road) | Pollard to a practical level |
| 0514 | Oak (Mature) At Gillamoor Road entrance | The Tomographic Survey carried out by Ian Barnes Associates identified internal decay in the main trunk in 2017. Whilst extensive decay was found it was determined that there was sufficient sound tissue to sustain the structural stability of the tree. However, the decay found is not a static situation and the amount of decay is likely to have increased over the past three years. Indeed Ian Barnes recommends that the tomographic survey is repeated this year. | It is strongly recommended that a further Tomographic survey be carried out this year to determine the current structural stability of the tree. |

Ryedale View Play Area, Kirkbymoorside.

| Ref No: | Species | Comments | Preliminary Management Recommendations |
|--|---|--|--|
| No number owing to difficulty in accessing | ash on NW boundary | Crown encroaching into neighbouring property | Crown reduces back to previous pruning cuts. |
| 0137 | Field maple NW corner | Large cavity in main trunk | Pollard to a point below cavity |
| 1459 | Pine North of garage block | Crown encroaching over neighbouring property | Crown lift over adjacent property to provide 4m clearance |
| 1463 | Hawthorn Southern boundary | Crown encroaching over neighbouring property | Crown lift over adjacent property to provide 2m clearance |
| No number owing to difficulty in accessing | 2No. Young ashes Southern boundary adj. to No.12 Ryedale Crescent | Very spindly tall trees. | Pollard to leave a short stump to regenerate a lower canopy and allow the adjacent oak space to develop. |
| 1467 | Pine Southern most pine, south west of 1459 | Leans heavily in a southerly direction, with evidence of bark buckling in the main stem. | Remove tree within the coming winter |

Old Road play area, Kirkbymoorside.

| Tree No: | Species | Comments | Preliminary Management Recommendations |
|----------|------------------|--|--|
| T1 | Ash | Semi-mature, die-back in ends of branches throughout the crown, possibly ash die-back disease, | Monitor – re inspect June 2021 |
| T2 | Lime | Semi-mature, healthy strong tree. Crown hanging low. | Crown lift to provide 2.5m clearance |
| T4 | Cut leafed alder | Young tree with co-dominant leaders. Crown on highway side growing close to overhead wires. | Reduce offending branches by a maximum of 1-metre. |
| T7 | Lime | Strong, early mature tree. Crown hanging over boundary hedge . | Crown lift of hedgerow side to clear the hedge by 1-meter. |

Sports field, New Road Kirkbymoorside.

| Ref No: | Species | Comments | Preliminary Management Recommendations |
|-----------------|----------------------------|--|---|
| 0166 | Poplar Eastern boundary | Large mature tree, large scar on southern side of main trunk hollowing in middle, Fruiting bodies of Amilllaria mellia (Bootlace fungus) | Consider felling during the coming winter. |
| 0167 | Poplar Easter boundary | Large mature tree, appears outwardly sound | Could ultimately be affected by the adjacent fungus as it can spread through neighbouring root systems. - Monitor |
| 0168 | Ash Eastern boundary | Extensive ivy growth on main stem | Sever ivy at the base of the tree to prevent encroachment into the crown. |
| 0169 (no 70) | Ash Eastern boundary | Extensive ivy growth on main stem | Sever ivy at the base of the tree to prevent encroachment into the crown. |
| 0171 | Ash Eastern boundary | Extensive ivy growth on main stem | Sever ivy at the base of the tree to prevent encroachment into the crown. |
| 0172 | Ash Eastern boundary | Extensive ivy growth on main stem | Sever ivy at the base of the tree to prevent encroachment into the crown. |