

Item EN Compliance	No	Surface EN Compliance	N/a
--------------------	----	-----------------------	-----



<b>Item</b>	Skate Area				
<b>Supplier</b>	Unknown				
<b>Surface</b>	Wood				
<b>Risk Rating Overall</b>	Very Low	Low	Medium	High	Unacceptable
				13	

### Findings at the time of inspection with risk number



	Broken glass evident. <b>Recommendation:</b> Consider removing broken glass and monitor area.	13
	Transition plates and riding surfaces lifting around whole site. <b>Recommendation:</b> Monitor to repair this condition.	12
	As above finding. <b>Recommendation:</b> As above Recommendation.	12
	Half pipe surface unstable. <b>Recommendation:</b> Monitor to repair this condition.	12

Item EN Compliance		Surface EN Compliance	
--------------------	--	-----------------------	--



<b>Item</b>					
<b>Supplier</b>					
<b>Surface</b>					
<b>Risk Rating Overall</b>	Very Low	Low	Medium	High	Unacceptable

### Findings at the time of inspection with risk number

	Cracks evident in riding surface. <b>Recommendation:</b> Monitor to repair this condition.	12
	Grind rail fixings loose on pyramid box. <b>Recommendation:</b> Consider to retighten loose fixing(s) as required.	13
	<b>Recommendation:</b>	
	<b>Recommendation:</b>	