




SOVEREIGN
Bringing imagination into play


Inspection Report For:




Inspection Location:



Inspected By:



Inspection Date:



SOVEREIGN DESIGN PLAY SYSTEMS LIMITED

40 TOWERFIELD ROAD

SHOEBURYNESSE

ESSEX

SS3 9QT

TEL: 01702 291129

www.sovereignplayequipment.co.uk

info@sovereignplay.com

Important Information

Sovereign Design Play Systems Limited inspectors are accredited to the RPII (Register of Play Inspectors International) and are qualified to carry out operational inspections on your behalf, for both Sovereign and other manufacturers' play equipment.

Operational inspections should be carried out at intervals not exceeding 3 months in unsupervised areas and 6 months in supervised areas.

Surfacing is solely assessed in terms of the area covered and its visible condition. We are unable to verify the groundworks undertaken and therefore are unable to advise conclusively.

We can only comment on the current condition of the equipment at the time of the inspection.

It is the owner/operator's responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

Routine inspections should be carried out daily or weekly depending on use by suitably trained staff that have a basic knowledge of playground equipment with the ability to identify/recognise potential hazards. A record to confirm the inspection has been completed and its findings should be kept to ensure your Sovereign Design Play Systems Limited warranties are upheld.

Please refer to our Operations and Maintenance Manual for further valuable information on the operation and maintenance of your equipment supplied by Sovereign.

Below is a risk assessment guide, however you should be aware there is no such thing as no risk.

High Risk

Equipment needs to be taken out of use until repairs are completed.

Medium Risk

Monitor use, any repairs need to be actioned within 3 months.

Low Risk

Monitor use, any repairs need to be actioned within 3 months.

Very Low Risk

Monitor use, no action needed.

Activity Tower

Low Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	Yes
Equipment Supplier:	Red Monkey	Equipment is without defect:	Yes
Equipment is labelled:	Yes		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance



Shelter

Low Risk



Surfacing Type:	Artificial Grass	Surfacing is without defect:	Yes
Equipment Supplier:	Sovereign Play	Equipment is without defect:	No
Equipment is labelled:	Yes		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to our Operation Manual for guidance on regular routine inspections and maintenance
Finding Two:	Staples/unused fixings were found in the timbers
Action(s):	Please remove staples unneeded fixings, as these can result in injuries
Finding Three:	Some of the timbers require replacing due to fatigue.
Action(s):	The affected timbers require replacing
Finding Four:	A timber is showing signs of movement. The fixing is pulling away from the connecting post.
Action(s):	Recommend adding a new fixing., Recommend the site maintenance team rectify this finding

Finding Five:

Guttering is showing signs of algae growth

Action(s):

Clean and treat appropriately



Activity Tower

Low Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	Yes
Equipment Supplier:	Red Monkey	Equipment is without defect:	Yes
Equipment is labelled:	Yes		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance



Shelter

Medium Risk



Surfacing Type:	Tarmac	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	No
Equipment is labelled:	No		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Finding Two:	Some of the timbers require replacing due to fatigue
Action(s):	The affected timbers require replacing

Finding Three:	Staples/unused fixings were found in the timbers.
Action(s):	Please remove staples unneeded fixings, as these can result in injuries

Finding Four:	The timber Infill holding the gutter pipe in place is showing signs of fatigue
Action(s):	Repair/replace as required





Shelter

Low Risk



Surfacing Type:	Tarmac	Surfacing is without defect:	Yes
Equipment Supplier:	Sovereign Play	Equipment is without defect:	No
Equipment is labelled:	Yes		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to our Operation Manual for guidance on regular routine inspections and maintenance
Finding Two:	Staples/unused fixings were found in the timbers
Action(s):	Please remove staples unneeded fixings, as these can result in injuries
Finding Three:	Gutter pipe is taped.
Action(s):	Recommend fixing guttering in place, Recommend the site maintenance team rectify this finding



SOVEREIGN
Bringing imagination into play



Log Climber

Low Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One:	The item is in good overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance
Finding Two:	Some of the timbers were showing air cracks (referred to as timber shakes)
Action(s):	This is a low risk finding and no remedial action is required at this time - monitor use



SOVEREIGN
Bringing imagination into play





SOVEREIGN
Bringing imagination into play

Scramble Net Climbers

Low Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	No
Equipment is labelled:	No		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance
Finding Two:	The rope was showing signs of wear
Action(s):	This is a low risk finding and no remedial action is required at this time - monitor use



SOVEREIGN
Bringing imagination into play





Activity Tower

Low Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	Yes
Equipment Supplier:	Sovereign Play	Equipment is without defect:	Yes
Equipment is labelled:	Yes		

Finding One:	The item is in good overall condition
Action(s):	Refer to our Operation Manual for guidance on regular routine inspections and maintenance
Finding Two:	Paintwork is showing signs of wear and corrosion.
Action(s):	This is a low risk finding and no remedial action is required at this time - monitor use



SOVEREIGN
Bringing imagination into play



Activity Panel

Low Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance



Tyre Climber

High Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	No
Equipment Supplier:	Unknown	Equipment is without defect:	No
Equipment is labelled:	No		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance
Finding Two:	Some of the timbers require replacing due to fatigue
Action(s):	The affected timbers require replacing
Finding Three:	The surface is showing signs of damage.
Action(s):	Repair/replace as required





Activity Frame

Medium Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	No
Equipment Supplier:	Unknown	Equipment is without defect:	No
Equipment is labelled:	No		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Finding Two:	The overall structure is showing early signs of movement. It is possibly due to the foundations becoming loose in the ground.
---------------------	---

Action(s):	Monitor use
-------------------	-------------

Finding Three:	The rope is showing signs of wear
-----------------------	-----------------------------------

Action(s):	This is a low risk finding and no remedial action is required at this time - monitor use
-------------------	--

Finding Four:	The equipment is showing signs of loose fixings.
----------------------	--

Action(s):	Recommend the site maintenance team rectify this finding
-------------------	--

Finding Five:

There are gaps opening between the surfacing and the edging surround or between the joints in the surfacing.

Action(s):

Monitor for any further deterioration and repair as required





Activity Trail

Low Risk



Surfacing Type:	Wetpour	Surfacing is without defect:	Yes
Equipment Supplier:	Lapsett	Equipment is without defect:	No
Equipment is labelled:	Yes		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Finding Two:	Some of the timbers were showing early signs of fatigue
Action(s):	This is a low risk finding and no remedial action is required at this time - monitor use

Finding Three:	Plastic post caps are showing signs of movement.
Action(s):	This is a low risk finding and no remedial action is required at this time - monitor use





Tyre Park

Low Risk



Surfacing Type:	Rubber Mulch	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Stage Area

Low Risk



Surfacing Type:	Tarmac	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	No
Equipment is labelled:	No		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance
Finding Two:	Some of the timbers require replacing due to fatigue
Action(s):	The affected timbers require replacing



SOVEREIGN
Bringing imagination into play





Play Huts

Low Risk



Surfacing Type:	Tarmac	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	No
Equipment is labelled:	No		

Finding One:	The item is in poor overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Finding Two:	Some of the timbers require replacing due to fatigue
Action(s):	Due to the age and deterioration of the equipment it would be uneconomical to repair., Recommend start planning for replacement equipment



SOVEREIGN
Bringing imagination into play



Ball Shooter

Low Risk



Surfacing Type:	Tarmac	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in moderate overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Spring Board

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Gym Frame

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One:	The item is in good overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Agility Table

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Ladders, Bench and Bars

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Crash Mat

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Benches

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in moderate overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Gym Frame

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One:	The item is in good overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance

Balance Tables

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	Yes
Equipment is labelled:	No		

Finding One: The item is in good overall condition

Action(s): Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance



Gym Mats

Low Risk



Surfacing Type:	N/A	Surfacing is without defect:	Yes
Equipment Supplier:	Unknown	Equipment is without defect:	No
Equipment is labelled:	No		

Finding One:	The item is in moderate overall condition
Action(s):	Refer to original suppliers Operation Manual for guidance on routine inspections and maintenance
Finding Two:	Some mats are showing signs of wear to corners and edges
Action(s):	This is a low risk finding and no remedial action is required at this time - monitor use



SOVEREIGN
Bringing imagination into play



