

Street	Column No	Col Type	Wattage	Priority	Works Required to meet adoption standard	Approx cost including elec labour (excl VAT)	Other information
Westfields	1	T/S	35	High	Loose in the ground, needs stabilisation. Painting required.	£500.00	Column currently located in Private Land so will need to be resited if NYCC are to adopt.
Westfields	2	T/S	35	High	Loose in the ground, needs stabilisation. Painting required.	£500.00	Column currently located in Private Land so will need to be resited if NYCC are to adopt.
Westfields	3	T/S	35	High	Loose in the ground, needs stabilisation. Painting required.	£500.00	Column currently located in Private Land so will need to be resited if NYCC are to adopt.
Westfields	4	T/S	35	Medium	Lantern needs re-aligning, Needs painting	£80.00	
Westfields	5	T/S	35	Low	Painting Required	£40.00	
Westfields	6	T/S	35	Low	Painting Required	£40.00	
Westfields	PB 7	Pole Box	70		No work required		
Westfields	PB 8	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles

West End	1	T/S	35	Medium	Re-align lantern and paint column	£80.00	
----------	---	-----	----	--------	-----------------------------------	--------	--

West Lund	1	T/S	35	low	Painting Required	£40.00	
West Lund	2	T/S	35	low	Painting Required	£40.00	
West Lund	3	T/S	35	low	Painting Required	£40.00	

A170	1	T/S	35	Medium	Needs DPI fitting and Column needs painting	£80.00	For these columns to be adopted 4 additional columns are required in order to meet road lighting standard.
A170	2	T/S	70		No work required		
A170	3	Concrete	35	High	Concrete column crack around door, complete new column needed	£1,000.00	
A170	4	T/S	35	Low	Painting Required	£40.00	
A170	5	T/S	35	Low	Painting Required	£40.00	

Duncombe Terrace	1	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
------------------	---	----------	----	--------	---	-----------	--

West Lund Lane	1	T/S	35	Low	Painting Required	£40.00	
West Lund Lane	2	T/S	35	High	Column needs lowering by 100mm and paint column	£500.00	Possible private land if so needs moving before it can be adopted
West Lund Lane	3	T/S	35	Low	Painting Required	£40.00	

Queens Way	1	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
Queens Way	PB 2	Pole Box	80	Medium	Complete new column needed	£1,000.00	Pole in private land column needed in highways land before it can be adopted
Queens Way	3	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	New column needs to be at the back of the footpath
Queens Way	4	T/S	35	Low	Painting Required	£40.00	
Queens Way	5	T/S	70	Low	Painting Required	£40.00	
Queens Way	6	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
Queens Way	7	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles

Vivers Place	2	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	
	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	

Old Rd	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Old Rd	PB 2	Pole Box	80	Medium	Column needed	£1,000.00	
Old Rd	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	
Old Rd	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	
Old Rd	5	T/S	35	High	Loose in the ground and column needs painting	£500.00	
Old Rd	6	T/S	70	Low	Painting Required	£40.00	
Old Rd	7	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	

Swinehead Lane	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Swinehead Lane	PB 2	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 5	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 6	Pole Box	80	Medium	Column needed	£1,000.00	

Church Street	1	T/S	35	Medium	Column needs painting and dropping 100mm	£500.00	
Church Street	2	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
Church Street	PB 3	Pole Box	80	Medium	replace column with complete new column	£1,000.00	Pole bracket un-maintainable

Crown Square	1	T/S	80	Medium	Column needs painting, XMAS DPI fitting and new lantern	£305.00	
Crown Square	3	T/S	80	Medium	Column needs painting, Fit new DPI and new lantern needed	£300.00	
Crown Square	PB 4	Wall Box	80	Medium	New box/lantern/Bracket needed	£600.00	
Crown Square	PB 5	Wall Box	80	Medium	New lantern needed	£220.00	

Car Park							We do not adopt decorative columns in car parks
----------	--	--	--	--	--	--	---

Tinley Garth	1	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
	2	T/S	70	Low	Painting Required	£40.00	
	3	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
	PB 4	Wall Box	80	Medium	New box/lantern/Bracket needed	£600.00	
	5	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	

	6	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
	7	T/S	35	Medium	Column needs painting, XMAS DPI fitting and new lantern	£305.00	

Adela Shaw	1						We will not adopt this as Adela Shaw is a private road
------------	---	--	--	--	--	--	--

Park Lane	1	T/S	35	Low	Painting Required	£40.00	
	2	T/S	35	Low	Painting Required	£40.00	
	3	T/S	35	Low	Painting Required	£40.00	

Sunnyside	PB 1	Wall Box	80	Medium	New box/lantern/Bracket needed	£600.00	
-----------	------	----------	----	--------	--------------------------------	---------	--

Castlegate	1	T/S	80	High	No access to column due to vegetation new lantern needed	£220.00	
Castlegate	2	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	

Dale End	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 2	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 5	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 6	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 7	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 8	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	9	T/S	35	Low	Painting Required	£40.00	
Dale End	10	T/S	35	Low	Painting Required	£40.00	

Dale End	11	T/S	35	Low	Painting Required	£40.00	
----------	----	-----	----	-----	-------------------	--------	--

Ryedale View	1	T/S	35	High	column needs painting column needs dropping 200mm	£500.00	
Ryedale View	2	T/S	35	Low	Painting Required	£40.00	
Ryedale View	3	T/S	35	Medium	Column in private land new column needed in highways land before it can b	£1,000.00	
Ryedale View	4	T/S	70	Low	Painting Required	£40.00	
Ryedale View	5	T/S	70	Low	Painting Required	£40.00	

Ryedale Crescent	1	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	2	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	3	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	4	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	5	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent F/P	1	T/S	80	Low	Painting Required	£40.00	

Manor Vale Lane	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
-----------------	------	----------	----	--------	---------------	-----------	---

Manor Close	No number	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
-------------	-----------	----------	----	--------	---	-----------	--

Ings Lane	1	T/S	70	High	Heavy corrosion new column needed	£1,000.00	
Ings Lane	2	T/S	35	Low	Painting Required	£40.00	
Ings Lane	3	T/S	35	Low	Painting Required	£40.00	
Ings Lane	4	T/S	35	Low	Painting Required	£40.00	
Ings Lane	5	T/S	35	Low	Painting Required	£40.00	

Keldholme West	1	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Keldholme West	2	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Keldholme West	3	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Keldholme West	4	T/S	35	High	Heavy corrosion new column needed	£1,000.00	
Keldholme West	PB 5	Pole Box	35	Medium	New box/lantern/Bracket needed	£600.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Keldholme West	PB 6	Pole Box	35	Medium	New box/lantern/Bracket needed	£600.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Keldholme West	PB 7	Pole Box	35	Medium	New box/lantern/Bracket needed	£600.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Keldholme West	PB 8	Pole Box	35				
Keldholme West	9	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Keldholme West	10	T/S	35	Low	Painting Required	£40.00	
Keldholme West	11	T/S	35	Low	Painting Required	£40.00	
Keldholme West	12	T/S	35	Low	column needs painting	£40.00	
Keldholme West	13	T/S	35	Low	Painting Required	£40.00	
Keldholme West	14	T/S	35	Low	Painting Required	£40.00	

Keldholme south	1	T/S	70	Low	Painting Required	£40.00	
Keldholme south	2	T/S	35	Low	Painting Required	£40.00	
Keldholme south	3	T/S	70	Low	Painting Required	£40.00	

Kirkby Mills	1	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Kirkby Mills	2	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Kirkby Mills	3	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	

The list below shows the streets that need extra columns to bring it upto lighting standards, t

<b>Street</b>	<b>Amount needed</b>	<b>Est Cost</b>
Keldholme	5	£5,000.00
A170	4	£4,000.00
Vivers Place	1	£1,000.00
Old Rd	1	£1,000.00
Swine Head	2	£2,000.00
Tinley Gar	2	£2,000.00
Meadow Vw	1	£1,000.00
Manor Cl	3	£3,000.00
Dale End	1	£1,000.00

this is only a rough guide as I need to put the streets through our design program