

	This work is recommended but is not essential
	Work required but not urgently
	Urgent work required

Street	Column No	Col Type	Wattage	Priority	Works Required to meet adoption standard	Approx cost including elec board (exc VAT)	Other information
Westfields	1	T/S	35	High	Loose in the ground, needs stabilisation. Painting required.	£500.00	Column currently located in Private Land so will need to be resited if NYCC are to adopt.
Westfields	2	T/S	35	High	Loose in the ground, needs stabilisation. Painting required.	£500.00	Column currently located in Private Land so will need to be resited if NYCC are to adopt.
Westfields	3	T/S	35	High	Loose in the ground, needs stabilisation. Painting required.	£500.00	Column currently located in Private Land so will need to be resited if NYCC are to adopt.
Westfields	4	T/S	35	Medium	Lantern needs re-aligning, Needs painting	£80.00	
Westfields	5	T/S	35	Low	Painting Required	£40.00	
Westfields	6	T/S	35	Low	Painting Required	£40.00	
Westfields	PB 7	Pole Box	70		No work required		
Westfields	PB 8	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles

West End	1	T/S	35	Medium	Re-align lantern and paint column	£80.00	
----------	---	-----	----	--------	-----------------------------------	--------	--

West Lund	1	T/S	35	low	Painting Required	£40.00	
West Lund	2	T/S	35	low	Painting Required	£40.00	
West Lund	3	T/S	35	low	Painting Required	£40.00	

A170	1	T/S	35	Medium	Needs DPI fitting and Column needs painting	£80.00	For these columns to be adopted 4 additional columns are required in order to meet road lighting standard.
A170	2	T/S	70		No work required		
A170	3	Concrete	35	High	Concrete column crack around door, complete new column needed	£1,000.00	
A170	4	T/S	35	Low	Painting Required	£40.00	
A170	5	T/S	35	Low	Painting Required	£40.00	

Duncombe Terrace	1	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
------------------	---	----------	----	--------	---	-----------	--

West Lund Lane	1	T/S	35	Low	Painting Required	£40.00	
West Lund Lane	2	T/S	35	High	Column needs lowering by 100mm and paint column	£500.00	Possible private land if so needs moving before it can be adopted
West Lund Lane	3	T/S	35	Low	Painting Required	£40.00	

Queens Way	1	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
Queens Way	PB 2	Pole Box	80	Medium	Complete new column needed	£1,000.00	Pole in private land column needed in highways land before it can be adopted
Queens Way	3	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	New column needs to be at the back of the footpath
Queens Way	4	T/S	35	Low	Painting Required	£40.00	
Queens Way	5	T/S	70	Low	Painting Required	£40.00	
Queens Way	6	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
Queens Way	7	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles

Vivers Place	2	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	
	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	

Old Rd	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Old Rd	PB 2	Pole Box	80	Medium	Column needed	£1,000.00	
Old Rd	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	
Old Rd	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	
Old Rd	5	T/S	35	High	Loose in the ground and column needs painting	£500.00	
Old Rd	6	T/S	70	Low	Painting Required	£40.00	

Old Rd	7	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
--------	---	----------	----	--------	---	-----------	--

Swinehead Lane	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Swinehead Lane	PB 2	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 5	Pole Box	80	Medium	Column needed	£1,000.00	
Swinehead Lane	PB 6	Pole Box	80	Medium	Column needed	£1,000.00	

Church Street	1	T/S	35	Medium	Column needs painting and dropping 100mm	£500.00	
Church Street	2	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
Church Street	PB 3	Pole Box	80	Medium	replace column with complete new column	£1,000.00	Pole bracket un-maintainable

Crown Square	1	T/S	80	Medium	Column needs painting, XMAS DPI fitting and new lantern	£305.00	
Crown Square	3	T/S	80	Medium	Column needs painting, Fit new DPI and new lantern needed	£300.00	
Crown Square	PB 4	Wall Box	80	Medium	New box/lantern/Bracket needed	£600.00	
Crown Square	PB 5	Wall Box	80	Medium	New lantern needed	£220.00	

Car Park							We do not adopt decorative columns in car parks
----------	--	--	--	--	--	--	---

Tinley Garth	1	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
	2	T/S	70	Low	Painting Required	£40.00	
	3	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
	PB 4	Wall Box	80	Medium	New box/lantern/Bracket needed	£600.00	
	5	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	

	6	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
	7	T/S	35	Medium	Column needs painting, XMAS DPI fitting and new lantern	£305.00	

Adela Shaw	1						We will not adopt this as Adela Shaw is a private road
------------	---	--	--	--	--	--	--

Park Lane	1	T/S	35	Low	Painting Required	£40.00	
	2	T/S	35	Low	Painting Required	£40.00	
	3	T/S	35	Low	Painting Required	£40.00	

Sunnyside	PB 1	Wall Box	80	Medium	New box/lantern/Bracket needed	£600.00	
-----------	------	----------	----	--------	--------------------------------	---------	--

Castlegate	1	T/S	80	High	No access to column due to vegetation new lantern needed	£220.00	
Castlegate	2	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	

Dale End	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 2	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 3	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 4	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 5	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 6	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 7	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	PB 8	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Dale End	9	T/S	35	Low	Painting Required	£40.00	
Dale End	10	T/S	35	Low	Painting Required	£40.00	
Dale End	11	T/S	35	Low	Painting Required	£40.00	

Ryedale View	1	T/S	35	High	column needs painting column needs dropping 200mm	£500.00	
Ryedale View	2	T/S	35	Low	Painting Required	£40.00	
Ryedale View	3	T/S	35	Medium	Column in private land new column needed in highways land before it ca	£1,000.00	
Ryedale View	4	T/S	70	Low	Painting Required	£40.00	
Ryedale View	5	T/S	70	Low	Painting Required	£40.00	

Ryedale Crescent	1	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	2	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	3	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	4	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent	5	T/S	35	Low	Painting Required	£40.00	
Ryedale Crescent F/P	1	T/S	80	Low	Painting Required	£40.00	

Manor Vale Lane	PB 1	Pole Box	80	Medium	Column needed	£1,000.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
-----------------	------	----------	----	--------	---------------	-----------	---

Manor Close	No number	Concrete	80	Medium	Concrete column, complete new column needed	£1,000.00	
-------------	-----------	----------	----	--------	---	-----------	--

Ings Lane	1	T/S	70	High	Heavy corrosion new column needed	£1,000.00	
Ings Lane	2	T/S	35	Low	Painting Required	£40.00	
Ings Lane	3	T/S	35	Low	Painting Required	£40.00	
Ings Lane	4	T/S	35	Low	Painting Required	£40.00	
Ings Lane	5	T/S	35	Low	Painting Required	£40.00	

Keldholme West	1	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
----------------	---	----------	----	--------	---	-----------	--

Keldholme West	2	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Keldholme West	3	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Keldholme West	4	T/S	35	High	Heavy corrosion new column needed	£1,000.00	
Keldholme West	PB 5	Pole Box	35	Medium	New box/lantern/Bracket needed	£600.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Keldholme West	PB 6	Pole Box	35	Medium	New box/lantern/Bracket needed	£600.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Keldholme West	PB 7	Pole Box	35	Medium	New box/lantern/Bracket needed	£600.00	North Yorkshire County Council will not adopt lighting units attached to wooden poles
Keldholme West	PB 8	Pole Box	35				
Keldholme West	9	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Keldholme West	10	T/S	35	Low	Painting Required	£40.00	
Keldholme West	11	T/S	35	Low	Painting Required	£40.00	
Keldholme West	12	T/S	35	Low	column needs painting	£40.00	
Keldholme West	13	T/S	35	Low	Painting Required	£40.00	
Keldholme West	14	T/S	35	Low	Painting Required	£40.00	

Keldholme south	1	T/S	70	Low	Painting Required	£40.00	
Keldholme south	2	T/S	35	Low	Painting Required	£40.00	
Keldholme south	3	T/S	70	Low	Painting Required	£40.00	

Kirkby Mills	1	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Kirkby Mills	2	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	
Kirkby Mills	3	Concrete	35	Medium	Concrete column, complete new column needed	£1,000.00	

Approx Total	£59,290.00
---------------------	-------------------