

Kirkbymoorside Town Council
Information for meeting on Monday 18 October 2021

8. Play Areas

b. II. To receive the quotation for remedial repairs identified as medium risk

6. Richter Cantilever Swing

Wetpour Surfacing - Repair 200mm² x 60mm deep

7. Richter 2.75m 1 Bay Swing with 2 Flat Seats

Replace one rotten support

Wetpour Surfacing - Repair 200mm² x 10mm deep

Playdale Quotation:

600mm 200mm Vertical Pole	£52.27	
Black Wet Pour Repair Kit (per m ² @ 20mm deep)	£175.00	
Spares Delivery & Installation	£495.00	= £929.45 (incl VAT)

12. Playdale Log & Net Climber

Wood Chippings surfacing -Require top up (actually 130mm deep, should be at least 300mm)

www.gravelmaster.co.uk Quotation:

3no. 1m³ bulk bag play grade bark @ £122.00 each (incl delivery and vat, excl labour) = £366.00

13. Playdale Trim Trail

Condition: Wobble log showing signs of rotting – monitor

Replace two rotten step posts

Streetscape Quotation:

2no. step posts @ £325 +VAT each including fitting and removal of existing

14. Ancillary items

Gate at toddler play area. Replace missing buffer on gate (Low Risk)

Gate between skatepark and play area: Re-adjust self-closing device as gate closing too fast (closing in 3 seconds, should be at least 5 seconds) (Medium Risk)

Pedestrian gates to skatepark –Clearance of between 60mm & 110mm should be maintained at bottom of gates. Replace one missing gate stop. Re-set gates (catches missing stoppers at two gates (Low Risk) Remove excess bolt thread. Replace one missing nut on bolt. Remove potential pinching/crushing hazard between gate & post at hinge side (a gap of at least 12mm should be maintained) (Medium Risk)

One pedestrian gate & one vehicular access gate to main area – remove potential pinching/crushing hazard at pedestrian gate (a gap of at least 12mm should be maintained) (Medium Risk)

Path satisfactory (Very Low Risk)

Response from Streetscape regarding remedial repairs to gates:

With regards to the gates we wouldn't be able to address all of the issues highlighted. The council could spend good money to try and address the issues and still have issues picked up the following year.

We would therefore recommend replacing the gates with steel self closing gates. These would cost £1795 +VAT per gate required, with price including carriage and any removal, disposal and making good costs.



Quotation awaited from Duncombe Sawmill.