Kirkbymoorside Town Council

Information for the Moorside Room Committee meeting on Wednesday 25 June 2025

Flooring Options

Ryedale Carpets

Thank you for asking me to quote for flooring at the Moorside Room. Areas included are the main room, entrance lobby, toilet and disabled toilet.

To prime and screed the sub-floor, re-trim 3x fire doors and supply and fit Polyflor Wood FX Safety Flooring would cost £3171.00 + vat.

Please feel free to call me with any questions.

Best Regards, Rod Farquharson.

Calverts Carpets

2 options of vinyl or Engineered oak so i have attached 2 quotes for you showing the 2 options.

Option 1 – Vinyl Supertex 2025 Argentina 542 4m £1,832.50 + VAT Fitting@ Pay fitter direct under separate contract £650

The vinyl quote is based on the existing floor being left in situ and the fitter doing a screed over the top to make sure it is level. I would suggest getting someone in prior to this just to test if there is any moisture in the stone tiles, if there is moisture you may need to have a damp proof membrane installed

moisture in the stone tiles, if there is moisture you may need to have a damp proof membrane installe first. The cost of the fitting is at the bottom of the quote and would be invoiced by the fitters direct as they are all self employed. The fitting charge is separate to our total for the materials.

Option 2 - 14/3mm Natures Own Engineered Oak - supply only £2.166.67 + VAT

It will be necessary to lift the stone tiles first otherwise you would be putting too much height on the floor as the oak is 14mm thick plus the underlay which is 2mm.

This would be the warmer option which seemed to be the main concern yesterday. Hope this helps,

Graham

Extract of Moorside Room Committee Minutes dated 4 November:

MR007 Housekeeping

- a. Snag list of remedial repairs needed:
 - Cover on electrical supply to the radiator in the entrance area loose (high priority) ✓
 - Mould growing on the bottom of the wall to left side of entrance door from inside

 ✓ most likely due to corner of coir entrance mat being waterlogged. Matting replaced and mould spray administered
 - # 3 top windows not closing ✓
 - Door to store cupboard difficult to open. The door needs to be adjusted and the addition of a handle.
 - Door to main room from foyer not opening fully when pulled back towards the entrance (Note: if underfloor heating is installed, doors will need altering, so maybe leave this for now) ✓
 - Floor tiles need re-grouting on hold pending any agreed works to the floor
 - Paint around inside of door to main hall badly chipped on hold pending completion of works to the property
 - Installation of shelves and hooks in the storage room n/a the area must be kept clear for stacking of storage items and chairs
 - Paint on back wall scuffed by chairs—on hold pending completion of works to the property
 - Holes in cover on #2 speakers ✓
 - One cupboard door not closing ✓ due to a large plate which has subsequently been moved to a deeper cupboard
 - Deep clean needed ✓

Schedule of bookings from 25 June 2025:

Every Monday evening 6 – 8pm – rehearsals

Sunday 29 June - Adventure Safe Training Day

Saturday 19 July – Repair Café

Sunday 27 July – Christening

Tuesday 29 & Wednesday 30 July – Adventure Safe Training Days

Friday 1 and Saturday 2 August – Kirkbymoorside Music Festival

Sunday 17 August – Adventure Safe Training Day

Saturday 6 and Sunday 7 September – Adventure Safe Training Days

Saturday 20 September – Repair Café

Thursday 25th September – Marie Curie Fundraising Event

Monday 13 October – John Stockton Education Foundation

Saturday 25 and Sunday 26 October – Give or Take Days

Saturday 22 November – Repair Café

Enquiries for regular bookings on Thursday mornings for weekly Makaton inspired music and story sessions for under 5s